

Sensor Part Number	Sensor Specifications			Controller Number																
	Base Resistance at 25°C	Interchangeable Tolerance	Single Point Tolerance																	
				5C7-582	5C7-361	5C7-362	5C7-550	5C7-350	5C7-195	5C7-252	5C6-357	5C6-323	5CX-500	5C1-147	5CX-147	5CX-371	5C5-90	5CX-754	5CX-153	
TS67	15K	±1.0°C over 0°C to 100°C		-20°C to 100°C	-20°C to 100°C	-20°C to 100°C	-20°C to 100°C	-20°C to 100°C	-20°C to 100°C	-20°C to 110°C			-20°C to 115°C	35°C to 75°C	-20°C to 115°C	-20°C to 115°C	35°C to 75°C	-20°C to 115°C	-20°C to 115°C	
TS91	10K	±1.0°C over 0°C to 100°C																		
TS104	50K	±1.0°C over 0°C to 100°C		0°C to 150°C			0°C to 150°C			0°C to 150°C										
TS136	15K	±0.1°C over 0°C to 70°C		-20°C to 100°C	-20°C to 100°C	-20°C to 100°C	-20°C to 100°C	-20°C to 100°C	-20°C to 100°C	-20°C to 110°C										
TS141	5K	±1.0°C over -40°C to 70°C		-40°C to 70°C						-40°C to 70°C										
TS165	231.5K	±1.0°C±1.5°C over 100°C to 250°C / 25°C to 250°C																		
TS133	200K	±2.0°C over 50°C to 225°C								50°C to 225°C										
TXOA	1.9K		±10% @25°C																	
TP10	1.2K		±10% @25°C																	
TP08	2K		±10% @25°C																	
TS08	2K	±1.0°C over -20°C to 50°C																		
TS09	2K	±0.5°C over -20°C to 50°C																		
TP20	2.7K		±10% @25°C																	
TX0	10K		±10% @25°C																	
TP30	7.3K		±10% @25°C																	
TP67	15K		±10% @25°C																	
TS54	15K	±0.5°C over 0°C to 100°C																		
TX1	30K		±10% @25°C																	
TP40	19.5K		±10% @25°C																	
TS55	45K	±0.5°C over 25°C to 125°C																		
TP50	48K		±10% @25°C																	
TX12	100K		±10% @25°C																	
TS82	100K	± 2°C over 75°C to 175°C																		
TS80	100K	±1.0°C over 75°C to 175°C																		
TS81	100K	±0.5°C over 75°C to 175°C																		
TX1A	200K		±10% @25°C																	
TP60	119K		±10% @25°C																	
TX2	740K		±10% @25°C																	
TX2A	1000K		±10% @25°C																	